

BWI Airport

Baltimore, MD

Using a mobile mixer, HP Cement was extended with gravel and sand to repair the light wells on the runway. HP Concrete was also used for various full depth repairs.

